

CYLON® TECHNICAL BULLETIN NO. 524

Issue Date: 27 October 2023

CB Line Firmware 9.2.6

Products Affected: CBT-3T6-5R, CBV-2U4-3T, CBV-2U4-3T-N, CBX-8R8, CBX-8R8-H, CBT-4T4-2U1R

Summary

This is an incremental update that fixes reported issues and adds enhancements.

Features

RESOLVED ISSUES

- With the **Duty Standby** module, short bursts of Trip signals are now ignored in order to avoid unintended Run/Alarm switching.
- In some rare use cases, setpoints could be lost following a reboot. This has been resolved.
- Resource error message is no longer displayed when performing a large number of CXpro^{HD} downloads to a controller.
- **Flash** storage usage has been optimized when making use of the **Runtime** module.

UPDATES

- A new **BACnet priority Manager** Module has been added.
- **Lighting/Blind** button operation has been simplified for **FusionAir** Module

Note: In order to configure these new firmware features, CXpro^{HD} v10.7.03 or later must be used.

Customer Impact

Customers wishing to access the new functionality must upgrade when as soon as convenient.

The firmware can be download from our support web sites:

- North America <https://cyloncommunity.com/>
- Europe/ROW <http://support.cylon.com/>