#### **TECHNICAL BULLETIN**

# Aspect v3.01.03

Issue Date: November 27 2017

Product: Aspect®

**Product Version:** 3.01.0.3

### **Summary**

This maintenance update release addresses CB / EC communications issues on the Aspect-Nexus™ platform.

## **Background**

This is a maintenance update for the **Aspect** v3.01.02 revision.

### **Features and Installation**

All files relevant to this release can be found on the <u>Dealer Toolbox</u> by visiting <u>Product Support</u> > Firmware Updates and <u>Product Support</u> > Software Updates

#### Installation

In order to take advantage of product enhancements and resolutions within Aspect v3.01.03, you must upgrade the firmware of your existing Aspect<sup>®</sup> target (Aspect-Matrix MAX<sup>™</sup>, Aspect-Nexus<sup>™</sup>, Aspect-Facility<sup>™</sup>, Aspect-Facility<sup>™</sup>, Aspect-Facility<sup>™</sup>, Description of the target.

Instructions on this process can be found in the **Aspect-Studio™** Online Help at any time. Once your target's firmware has been updated, you must then open your existing project using **Aspect Studio** v3.01.03. Perform a Clean and then deploy your project to the target. This process **must** be done to ensure your project files receive all enhancements and updated drivers included as part of this maintenance release.

#### **Resolved Issues**

**ASP-4496** 

Packet collision issues between **CB controllers/Engineering Center** and **Aspect-Nexus™** devices when communicating at 76.8k baud have been resolved.

## **Customer Impact**

Customers using **Aspect-Nexus™** at 76.8k baud on existing Sites should upgrade to this version. All future installations should use this version or later.

