

AspectFT v2.04.01 Revision Notes

02/24/2015

American Auto-Matrix is pleased to announce the release of AspectFT v2.04.01! This release includes several new features and capabilities that reduce setup, engineering time, and work required to setup an AspectFT project. This document provides full release notes regarding the release.

All upgrade files relative to this release can be found on the **AAM Toolbox** by visiting **Product Support>Firmware Updates**.

Upgrade Notes

- In order to take advantage of product enhancements and resolutions within AspectFT v2.04.01, you must upgrade the firmware of your existing AspectFT target (AspectFT-Matrix™, AspectFT-Nexus™, AspectFT-Facility™, AspectFT-Enterprise™) using the System Update feature within the WebUI of the target. Instructions on this process can be found in the AspectFT-Studio™ Online Help at any time.
- Once your target's firmware has been updated, you must then open your existing project using AspectFT-Studio v2.04.01. Perform a Clean and then deploy your project to the target. This process must be done to ensure your project files receive all enhancements included as part of this maintenance release.

New Features

- AspectFT-Studio™
 - A reference name attribute has been added to Map Point Elements. This enhances transfer with context functionality.
 - The ability to time stamp signed code from the Jar signing utility has been added
- New Hardware Support
 - Support for the new AspectFT-MatrixMax[™] hardware platform

Notes:

In order to read individual priority array elements in eSC Controllers, the Read Property Multiple max in the Map BACnet device must be set to 1

Access to eSC Controllers must be activated via the WebUI in the AspectFT device (Communications Setup / BACnet / BACnet Settings

Resolutions

- Reads/write attempts via the SDP protocol would occasionally fail on deployed projects. Resolved
- BACnet Time Sync commands were not being issued from AspectFT targets according to the interval set in the WebUI under *Communication Setup > BACnet > Time Sync Settings*. **Resolved**
- In some situations, Map config properties were not being set properly and as a result did not persist in deployed projects. **Resolved**

If you have any further questions or require additional information, please contact the American Auto-Matrix Technical Support Department via email or at 1-877-AAM-PROS.