CBXi Firmware update 8.1.3

Summary

The **CBXi** range of controller firmware has been updated from `8.1.2` to `8.1.3` to fix an issue with downloading the **SiteGuide** program from **CXpro^HD** failed when the controller already had an existing **SiteGuide** program.

Background

The specific issue was reported following a **CBXi** upgrade in the field to `8.1.2` from a previous release.

Features

Resolved Issues

SYSX-270   This update fixes an issue that was introduced in `8.1.2` where downloading the **SiteGuide** program from **CXpro^HD** failed when the controller already had an existing **SiteGuide** program. This happened following a **CBXi** upgrade in the field from a previous release, e.g. `8.1.0`. Controllers shipped new from the factory with `8.1.2` are not affected by this issue.

Customer Impact

Customers who upgraded in the field from `8.0.0` (or earlier) to `8.1.2`, should upgrade to this version as soon as possible.

> **Note:**   The process of upgrading to this firmware revision can trigger an automatic strategy wipe on any controller running firmware older than `8.0.0`.

The firmware can be download from our support web sites:

- North America http://www.cylon-automatrix.com/login
- Europe/ROW see http://support.cylon.com/

Contact support@cylon.com for further information.

Cylon CONTROLS