MatrixPNC 1.09

Issue Date: 3/10/2017
Product: MatrixPNC
Product Version: 1.09

Summary

American Auto-Matrix is pleased to announce the release of MatrixPNC 1.09. This release resolves stability issues that may occur under heavy network loads and as well as issues with SPL programs.

Background

This is a maintenance update for the MatrixPNC product. The new version applies to both legacy Matrix hardware platform (part # MATRIX-PNC-DP) as well as current MatrixMax hardware platform (part # MATRIX2-PNC-DP).

Features and Installation

All files relative to this release can be found on the Dealer Toolbox by visiting Product Support > Firmware Updates. No updates to technical documentation were involved as part of this maintenance release.

Installation

In order to take advantage of product enhancements and resolutions within **MatrixPNC** v1.09, you must upgrade the firmware of your existing Aspect target using the System Update feature within the WebUI of the target.

CAUTION:

Upgrading to this release will not restore the controller to initial factory values by default. However, it is good practice that you backup your device configuration (capture file, compiled SPL programs, and database backup via WebUI) to protect against the unlikely event that data is lost.

Resolved Issues

- The %P attribute in Program Channels is now available when custom attributes are loaded.
- System stability has been improved when the network queue was under heavy loads.
- Local program attributes can now be accessed by other local programs. Program attributes in programs previously had to be added to the Point database in order to be accessed.

Customer Impact

Customers interested in taking advantage of the issue resolutions outlined above should upgrade when convenient.