

---

## CYLON® TECHNICAL BULLETIN NO. 510

Issue Date: 15 March 2023

# FBVi, FBTi, FBXi, CBXi Firmware 9.2.3

Products Affected: FBXi-X256, FBXi-X48, FBTi-7T7-1U1R, FBVi-2U4-4T-IMP, FBVi-2U4-4T-SI, FBVi-2U4-4T, FBVi-2U4-4T-FA-IMP, FBVi-2U4-4T-FA-SI, CBXi-8R8, CBXi-8R8-H

## Summary

This is an incremental build from the previous version that fixes reported issues and adds enhancements.

## Features

This release adds support for the soon to be released FBTi-6T1-1U1R, FBXi-8R8-X96 and FBXi-8R8-H-X96.

### RESOLVED ISSUES

- An incorrect menu option, which appeared inadvertently from web interface, has been removed.
- Performance when reading full Trend Logs using CXpro<sup>HD</sup> Datalog Manager has been improved.
- Full Upload/Download (FUD) operation has been enhanced.
- Device Discovery process now avoids sending excessive who-is requests.
- FUD upload no longer fails after the system had been idle for extended period.

## Customer Impact

Customers wishing to use this latest firmware for their controllers can upgrade when as soon as convenient.

The firmware is available from Global SBS Support ([global-sbs.support@abb.com](mailto:global-sbs.support@abb.com)) or <https://cyloncommunity.com/> (North America)