Technical Bulletin

MatrixPNC 1.08

Issue Date: Mar 4, 2016
Product: MatrixPNC
Product Version: 1.08

Summary

American Auto-Matrix is pleased to announce the release of MatrixPNC 1.08. This release resolves performance issues that may occur when SPL and Aspect Communications can flood the driver and cause it to fail.

This release also provides support for the forthcoming release of the MatrixPNC running on the Matrix MAX hardware platform.

Upgrade Notes

Firmware files can be downloaded by logging into the <u>Dealer Toolbox</u> and visiting <u>Product Support>Firmware Updates</u>. No updates to technical documentation were necessary as part of this maintenance release.

CAUTION:

Upgrading to this release will not default enable the controller to initial factory values however, it is good practice that you backup your device configuration (capture file, compiled SPL programs, and database backup via WebUI) in the unlikely event that data is lost.

New Features

• Support for the Matrix MAX platform. This is a new product that will be released via an upcoming product

Resolved

 An issue where SPL and Aspect Communications can flood the driver causing it to fail and not restart automatically.

