

Aspect 2.06.01

Issue Date: Feb 18, 2016

Product: Aspect Product Family

Product Strategy: 2.06.01

Summary

American Auto-Matrix is pleased to announce the release of Aspect v2.06.01!

This release specifically addresses issues identified when integrating with Teletrol devices. Please note that it is not necessary to update Aspect projects that are not communicating to eSC or TSC device. All upgrade files relative to this release can be found on the [Dealer Toolbox](#) by visiting [Product Support > Firmware Updates](#).

Upgrade Notes

In order to take advantage of product enhancements and resolutions within AspectFT v2.06.01, you must upgrade the firmware of your existing Aspect target (Aspect-Matrix MAX™, Aspect-Nexus™, Aspect-Facility™, Aspect-Enterprise™) using the System Update feature within the WebUI of the target.

Instructions on this process can be found in the Aspect-Studio™ Online Help at any time. Once your target's firmware has been updated, you must then open your existing project using Aspect Studio v2.06.01. Perform a Clean and then deploy your project to the target. This process must be done to ensure your project files receive all enhancements included as part of this maintenance release.

Resolved

- eSC devices located on remote IP subnets could not be reached by Aspect platforms. Support has been added for these eSC devices via a list found in the Aspect webUI under *Communication Setup > BACnet > eSC Device List*.
- TSC points in the Map could not be written to using Signed integer values.