Aspect v3.01.02

Issue Date: September 29, 2017 Product: Aspect[®] Product Version: 3.01.02

Summary

This maintenance update release addresses several issues present in the v3.01.00 of **Aspect**. Specifically, issues with **Aspect** Schedules, **Aspect-Matrix MAX[™]** 76.8k communications issues, as well as numerous **Aspect** enhancements. This update also includes the previously issued "WebServer SSL Patch" to prevent YUM updates from making **Aspect-Nexus[™]**, **Aspect-Facility[™]** and **Aspect-Enterprise[™]** targets unresponsive.

Background

This is a maintenance update for the Aspect v3.01.00 revision.

Features and Installation

All files relative to this release can be found on the <u>Dealer Toolbox</u> by visiting Product Support > Firmware Updates and Product Support > Software Updates

Installation

In order to take advantage of product enhancements and resolutions within Aspect v3.01.02, you must upgrade the firmware of your existing Aspect[®] target (Aspect-Matrix MAX[™], Aspect-Nexus[™], Aspect-Facility[™], Aspect-Fac

Instructions on this process can be found in the **Aspect-Studio**[™] Online Help at any time. Once your target's firmware has been updated, you must then open your existing project using **Aspect Studio** v3.01.02. Perform a Clean and then deploy your project to the target. This process **must** be done to ensure your project files receive all enhancements and updated drivers included as part of this maintenance release.

Resolved Issues

- ASP-4334 A conflict between stunnel and Apache mod_ss1 has been resolved.
- ASP-4337 Aspect-Matrix MAX[™] 76.8k baud rate MSTP communications have been resolved.
- ASP-4338 A communications issue with more than 128 BACnet devices on a single system has been resolved.
- ASP-4340 Graphic Binding Migration is now retained when it is not followed by other changes.
- ASP-4341 Map Schedule Properties are now writable. Properties for iCal/Exchange schedule types are now retained.
- ASP-4342 Importing a graphic from an external Map no longer fails when the imported graphic contains a Style that isn't present in the project.



Technical Bulletin September 29, 2017Error! Reference source not found.: Aspect v3.01.02

ASP-4344	System Home label is now settable.
ASP-4353	BACnet custom ping now accepts properties delimited by semicolon.
ASP-4354	BACnet Object discovery now works for devices with destination lengths > 1.
ASP-4356	Persistence error resolved for MapGraphics.
ASP-4371	MapRef ghost points now ignore leading whitespace.
ASP-4376	Orphaned points in database no longer cause issues with valid network points.
ASP-4388	Proxied Alarm priority now set correctly.
ASP-4393	Handling of sub-address error messages from Modbus IP gateways has been approved.
ASP-4394	Modbus driver maxConnections property is now set correctly.
ASP-4395	Authentication/Authorization issues have been resolved on targets that do not have a deployed project.
ASP-4392	SQLite database connections in Aspect-Studio [™] are no longer invalid after import of mapconfig.db
ASP-4407	Misconfigured network properties in Modbus points no longer throw runtime exceptions.
ASP-4437	URL Links in "GreenScreen Mode" no longer cause navigation to the Desktop.
ASP-4441	BACnet weekly schedule distribution now handles EOD correctly in all cases.

Enhancements:

ASP-4335	Optional visual indication of available click action has been added to Annunciator.
ASP-4339	Graphics Editor preview now updates when Image element is copied.
ASP-4350	Custom ping data type has been added to Network Device.
ASP-4363	eMap export of network point alarm priority is now available.
ASP-4387	New " remote graphic full screen " click action on annunciator.
ASP-4391	A new option has been added to override displayed name of context-based graphics.
ASP-4397	AspectStudioAPI has been upgraded for use with Aspect 3.01.x.

Customer Impact

Customers affected by any of the above issues should upgrade to this version. Also, any customers using Aspect-Nexus[™], Aspect-Facility[™] or Aspect-Enterprise[™] and wishing to take advantage of Aspect[®] 3.01 features or planning to use iCal[®] should should upgrade to this version.



Subject to change without notice ©2017 American Auto-Matrix All Rights Reserved WWW.AAMATRIX.COM B0228US rev 9 Issued by Product Development